



Canada–France–Hawaii Telescope Megacam L1 Restoration



Tom Benedict




U.MP9301






After Cleaning



Before Cleaning



1.8e+02

2e+02

2.2e+02

2.4e+02


2.6e+02


2.8e+02

3e+02

3.1e+02


3.3e+02

















One ring to make them off and in the direction had them

2 204-208 LI early damage
6 Area marked 1 and 2 had 0.78 spectrom of Sol 610-0171

H-1





Thanks To:

CFHT Management, Staff, Scientific Community

Ohara Glass

Stephan Gwyn of NRC-Hertzberg

John White of Gemini Observatory

